

**MX000001-OJE-I&C-002 Packet Content List (Deviation Meter Replacement)**

1. This document.
2. Meter, deviation, .4-0-.4 V DC, 50-185014NDND1AAD tagged as “Existing”.
3. Meter, deviation, .4-0-.4 V DC, 50-185014NDND1AAD with Acceptance Tag attached.
4. Work Order Task Number 00000302.
5. Work Order Instructions for Work Order 00000302.
6. Issue Ticket for Work Order 00000302.
7. OJT Instructor instructions for specifics of this packet.  
(MX0000001-OJE-I&C-002)

